



## Agricultural Land Classification Wanlip Sewage Works - Options, Leicestershire



### Legend

	Quality	SITE 1	SITE 5	SITE 6
Grade 1	Excellent	nil	nil	nil
Grade 2	Very Good	4.0	3.6	5.8
Grade 3a	Good	2.3	3.5	1.2
Grade 3b	Moderate	nil	1.2	1.2
Grade 4	Poor	nil	nil	nil
Grade 5	Very Poor	nil	nil	nil
	Agricultural land not surveyed	nil	nil	nil
	Other land	nil	0.2	0.5
	Boundary of survey area			
Total agricultural land area		6.3	8.3	8.2
Total survey area		6.3	8.5	8.7



Further details contained in MAFF (1988) Agricultural Land Classification of England and Wales - Revised guidelines and criteria for grading the quality of agricultural land. Maff (publications), London SE99 7TP. The information is accurate at base map scale but any enlargement would be misleading. Reproduction in whole or in part by any means is prohibited without the prior permission of MAFF.

Surveyed and drawn by the Resource Planning Team, FRCA, Cambridge

Based on the 1985 Ordnance Survey 1:10 000 map with the permission of the Controller of Her Majesty's Stationery Office. Unauthorised reproduction infringes Crown copyright: and may lead to prosecution or civil proceedings. MAFF Licence No: GD272361

Source map(s): SK5ISE  
Reference no: 087/98

© Crown Copyright Reserved 1999

Due to open  
Dec 1995

